

B. Milestone Chart



C. Cost Summary



D. Issues and Problems

- NEW GEOPHYSICAL TRUCK RECEIVED
- BANK STORAGE DOCUMENTAITON DELAYED
- AQUIFER TESTING DOCUMENTATION ON SCHEDULE BUT FIELD WORK DELAYED DUE TO WEATHER
- FUNDING FOR VTT MODEL UPDATE TAKEN FROM ROUTINE TECHNICAL SUPPORT