Battelle
Pacific Northwest Laboratories

Project Number _____

Internal Distribution

SM Brown
PA Eddy ✓
LB/ELH/File

Date February 20, 1981

To Chuck Cline

From E. L. Hilty

Subject INPUT FOR FEBRUARY "81" MONTHLY REPORT

A. Well Maintenance

1. Sample pump problems: The following wells were listed as having submersible pump problems by Environmental Monitoring sampling personnel:

699-8-32- a 110V plug was replaced by a 220V plug and the pump is now operational.

699-35-78- Couldn't find any problem here-pump O.K.

699-37-43- Pump not working - will be pulled, repaired, and replaced soon.

699-40-33- Pump was pulled by Rockwell and replaced with one of their own. Our equipment has been picked up and stored.

699-45-4 - A "sanding" problem has been taken care of and the pump is working O.K. now.

699-46-4 - This well has completely "sanded in" and cannot be sampled. The pump will be removed if we can get it out of the sand.

699-83-47- This pump also experienced "sanding" problems but was pulled, repaired, and replaced. Now working O.K.

2. New pump installations were established in well 699-S31-1 and 399-3-6.

3. Our "A" frame truck with the new "Jib-Boom" extension is back in service and appears to be working good. We now have a 25' boom capacity for our pump work.

4. The portion of the "81" well maintenance contract having to do with the specific wells to be worked on was completed and forwarded.

ELH/sr/44

54-1900-001 (3-71)
U S GOVERNMENT PRINTING OFFICE 1981—796-298 9