- Geophysical Characteristics (Cont'd.)

  Maintenance - The sonic, natural gamma and SP&R probes were repaired, tested in the standard well (399-5-2), and put back into service. The caliper probe is in the shop for repair now.

- Geophysical Log Interpretation

  Work has started on the software outlined in the June Monthly Report. While the VAX system is still not completely "up", it is still hoped that the software can be completed by the end of the month.

  Documentation has begun on the users' manual for the system.

  We have also been in communication with Steve Strait of BWIP - Rockwell on interfacing the two systems. A meeting will be held early next month to work out some details and examine the possibilities.

- Bank Storage

  See J. T. Rieger's Monthly Report.

- Aquifer Testing

  See L. S. Prater's Monthly Report.

- VTT Update

  Task completed.

Credit Card Calls

A call was made to Jim Herrick of Computalog-Gearhart, Calgary, Alberta, charged to phone 376-4808.

CSC:gd