- Aquifer Testing (Cont'd.)

  test was interrupted for about an hour when a small "dust devil" knocked over the electrical board and caused a fuse to blow. In spite of that mishap and the fact that the well devoured our electrical tapes, the test went smoothly. A more detailed account of the test results will be prepared soon.

- VTT Model Update

  A draft report has been written on the VTT update. This report will be retained as an open-file report. Because of incomplete funding, it will not be published.

PAE:CSC:LSP:JTR:sc