Geophysical Log Interpretation

Several logs for each of three deep holes DC-12, DC-14, and DC-15 were digitized and entered into the data base structure.

Initial programming was done on routines for plotting logs out of the data base.

Several "bugs" in the DIGLOG 1 and LOGHDR programs were encountered as more diverse well logs were digitized. Several hours of debugging time was required to modify the programs; however, they are running smoothly at this time.

Supporting Services

- A 30 kW generator was transferred to us from Atmospheric Sciences.
- The 615 Building was obtained for storage of equipment.

Safety Note

- Well 699-49-95, an old well which had caved in very badly has been filled with gravel, thereby averting a potential safety hazard.

DOE Credit Card Calls

- Nothing to report.

PAE:sc