Battelle
Pacific Northwest Laboratories

Project Number

Internal Distribution

PJ Blumer
[redacted]
MJ Sula
File
LB

Date July 27, 1981

To PE Bramson

From MR Quarders MRQuarders

Subject Monthly Report - July 1981

Due to opening the new gate house at Yakima Barricade, the power has been disconnected to our sampling location. Arrangements are being made to have power restored.

The timer at 300 san water sampler quit working and is being repaired. Other spare timers that had been repaired also would not work.

The new road monitor is still having electrical problems. Every time the brake pedal is used, it causes a peak on the chart.

The following test wells were not sampled for various reasons.

699 29-78	wire off plug
699 35-70	will not pump
699 38-70	will not pump
699 09-E2	pipe broken
699 17-05	pipe broken
399 03-12	no access road
399 04-01	recorder on well

All well problems reported for repair.

An Environmental Monitor picked up a lead brick from a Battelle employee that was found in his yard. The brick was reading 1000 c/m direct with approximately 200 c/m smearable, no alpha contamination was detected. The follow up surveys were completed by Radiation Monitoring Section.

DOE credit calls
Nothing to report

MRQ:lb