For Approval Of

Name	Approved	Date
PA Eddy	PAE	3-6-84
PE Bramson	PE Bramson PAE	3-6-84

Project Number _____

Internal Distribution

PE Bramson
PA Eddy
FILE
LB

March 6, 1984

Walter P. Ward
In-Situ, Inc.
209 Grand Avenue
Laramie, WY 82070

Dear Mr. Ward:

Enclosed is the SE 1000 transducer we discussed in our telephone conversations on March 5, 1984. Please note, the cable has been spliced together 5-6 feet from the transducer. This repair was needed as a result of the cable becoming entangled in a boat prop. The splice was then covered with heat shrink wrap and electrical tape. However, water could have worked its way into the transducer before the cable was found.

Please notify me of the damages and repair costs as soon as possible.

Sincerely,

Terry L. Liikala

T. L. Liikala
Scientist
Environmental Evaluations
Section

TLL:gd