Several special test well samples were collected for RHO and turned in to U.S. Testing and 329 lab.

There were no major problems with wells this month. Several wells pumped slow or dry before completion of pumping time but that can be avoided by valving down the flow of water.

MRQ:lb