The following wells were not sampled for various reasons:

199 N-04	well buried
199 N-05	new trench, could not get to well
199 N-16	dry
199 N-22	dry
199 N-25	dry
199 N-26	dry
199 B5-1	buried - EL Hilty working on this one
699 2-3	pump test equipment still in well
699 36-46P	blower - truck in shop all month waiting for parts
699 36-46Q	blower - truck in shop all month waiting for parts
699 72-98	dry

MRQ:1b