Name	Signature	Date
PA Eddy	PAE	7-18 83
PE Bramson	PEB	1-18-83

PE Bramson
PA Eddy
FILE
LB

July 18, 1983

Ben Everson
Underground Surveys Corp.
4973 E. Lansing
P.O. Box 12891
Fresno, CA 93727

Dear Mr. Everson:

The oil filled television light head has been returned to you for repair. Oil from the reservoir was forced up through the electrical connection into the camera case. Also the plastic reservoir is cracked. We had logged a well to 3538 ft when this happened. The water level is 500 ft below surface.

The new hydraulic motor we have installed on the winch is a Char-Lynn (Eaton) model 101-1007-007. The counterbalance valve is a Modular Control Co. valve #MCU 1-10-5-4-36.

Sincerely,

Vern L. McGhan
Sr. Technical Specialist
Environmental Evaluations Section

VLM/gd