Battelle
Pacific Northwest Laboratories

Project Number

Internal Distribution

PJ Blumer
PA Eddy
MJ Sula
File
LB

Date June 24, 1982

To PE Bramson

From MR Quarders

Subject Monthly Report - June 1982

Priest Rapids sampler was out of service due to maintenance on the generating unit. We received no sample on May 25 and June 8, which is the date it returned back to service.

The noble gas sampler at Sunnyside was returned for maintenance on May 26. It has not been put into service yet.

As requested by DOE, emergency monitoring equipment was photographed and slides prepared for their use.

One area approximately 3'x 3' at the N.W. corner of 100 B retention basin fence, was found contaminated to 800 c/m. The area was painted yellow and Larry Diediker of UNC was notified.

Monitoring trips were rescheduled for changes in milk, vegetables, and fruit sampling. The changes are to be effective in July.

Bill Jaquish and Tom George started working for the summer. They will be installing poles and signs at test well sites.

The following test wells were not sampled. Ed Hilty was informed and repairs are being completed.

699 8-32 pump not working
699 31-31 pump not working
699 32-42 dry
699 33-56 pump not working

The PQ&R pipes for well 699 14-E6, were buried by WPPSS while building a training course for their security personnel

DOE credit cards
Nothing to report

MRQ:lb

54-1800-001 (3-71)
☆ U.S. GOVERNMENT PRINTING OFFICE: 1981—796-298/9

1KLBH000 )0