Project Number

Internal Distribution

PJ Blumer
PA Eddy
MJ Sula
File
LB

Battelle
Pacific Northwest Laboratories

Date April 26, 1982

To PE Bramson

From MR Quarders

Subject Monthly Report - April 1982

Environmental monitoring collected some special air samples because of some problems RHO had at 200 E, B plant.

The Hanford water sampler is operating again. The bearing were frozen in the pump.

One noble gas sampler is in operation at the 300 area pond.

The fence was down around the Berg Ranch air sampling location and the cattle had tripped over our equipment. S.R. Bivins put everything back in operation and repaired the fence.

A special resurvey of all locations for pigeon droppings revealed no new contamination.

The readings around 377 building (steam generator) are about the same, 700 uR/hr at fence, 120 uR/hr at roadway.

The Riverview meat sample was not collected. It will be collected as soon as a location can be found.

The following test wells were not sampled for various reasons. Ed Hilty was notified.

699 19-88 pump blew fuses on generator
699 36-61A pump is not working
699 32-62~~0~~ p-tube dry
699 54-57 equipment in well

The usual RHO wells were not sampled this month. Scott Wilbur will be notified.

DOE credit calls
Nothing to report

MRQ:lb

54-1900-001 (3-71)
☆ U.S. GOVERNMENT PRINTING OFFICE: 1981—796-298/9

1L1BH000 )0