Battelle
Pacific Northwest Laboratories

Project Number_____

Internal Distribution

PJ Blumer
PA Eddy
MJ Sula
File
LB

Date February 22, 1982

To PE Bramson

From MR Quarders

Subject Monthly Report - February 1982

Larry Belt has left the Environmental Monitoring Section via the bump procedure set up with Radiation Monitoring. Kelly Byrne has replaced him. This is something new and different for the Environmental Monitoring Section.

The routine surface program is on schedule. We had Richland, 300 area, Hanford, and Priest Rapids Dam all working for once. Everything has finally thawed out.

There were seven road monitor trips completed and eighteen waste sites surveyed this month.

The reading around the 337 building have been holding about the same. The 3705 TLD location is 20 uR/hr, fence 900 uR/hr, and edge of the road (Route 4-S) 110 uR/hr.

The following Rockwell test wells were not sampled. Well numbers and reasons were reported to Scott Wilbur of Rockwell.

299E -	16-1	dry
	16-2	pump not working
	13-20	casing plugged
	24-8	pump not working
	25-6	pumped dry for 5 minutes
	28-5	pump not working
299W -	10-1	new fence, has no gate opening
	11-15	pump not working
	14-2	new fence, has no gate opening
	18-18	pump not working
	19-4	casing plugged

No problems with 699 wells this month.

DOE Credit calls
Nothing to report

MRQ:lb

54-1800-001 (3-71)
☆ U.S. GOVERNMENT PRINTING OFFICE: 1981—796-298/9