Battelle
Pacific Northwest Laboratories

Project Number_____

Internal Distribution

PJ Blumer
PA Eddy
MJ Sula
File
LB

Date September 24, 1981

To PE Bramson

From MR Quarders MR Quarders

Subject Monthly Report - September 1981

On August 25 and 26, D.O.E. conducted a QA audit of Environmental field work. M. R. Quarders accompanied them while they observed the monitors taking samples.

Test wells are now on schedule. We used both trucks and completed last months samples also. The following wells were not sampled.

199	B4-1	Bad pump
199	B5-1	Lid smashed on well
399	3-12	Unable to get to well
399	4-7	Equipment on well
699	19-58	To sandy
699	24-46	To sandy
699	25-55	To sandy
699	33-56	To sandy
699	34-41	To sandy-stuck
699	40-33	Electrical problems
699	48-7	Bad pump
699	72-88	Bee hive in well
699	S6-E14	Hole in pipe

All wells needing maintenance were reported to Ed Hilty.

UST complained about not having enough vegetation, so we resampled all annual vegetation locations.

All summer workers have left for school. Peace and quiet again.

300 san water sampler at 315 building has been plumbed into the Raw water line.

We are using the old Road Monitor again. Unknown problems with the new one.

We ran out of our sample pumps several times this month. Had 12 pumps in reserve so told the shop not to repair any more till after October 1. Would have turned out nicely, except 6 of the 12 repaired ones would not work. The shop foremen was notified of the lousy work. We are using the new ones that just came in. Hopefully they have all the problems fixed on them.

DOE credit calls
Nothing to report

MRQ:lb

54-1900-001 (3-71)
☆ U.S. GOVERNMENT PRINTING OFFICE: 1981—796-298/9