Battelle
Pacific Northwest Laboratories

Project Number

Internal Distribution

PJ Blumer
PE Eddy
MJ Sula
File
LB

Date May 26, 1981

To PE Bramson

From MR Quarders

Subject Monthly Report - May 1981

The quarterly railroad survey was completed this month. No contamination was detected.

Environmental monitors sampled three road killed deer and three radio collared deer that were sacrificed this month.

M.R. Quarders and six monitors worked a saturday and sunday surveying the proposed reactor site for Pacific Power and Light. All measurements were below detectable limits.

The following test wells were not sampled for various reasons.

199 B3-1	pump not working
699 69-38	p-tube plugged
699 66-38	p-tube dry
699 26-89	no power for irrigation pump
699 54-42	casing shifted cannot get bailer into well, needs pump

All these well problems were reported to Ed Hilty.

A safety meeting was held with Environmental monitors on May 13, 1981.

All routine environmental work is on schedule.

DOE credit calls
Nothing to report

MRQ:lb