Battelle
Pacific Northwest Laboratories

Project Number_____

Internal Distribution

CS Cline
PA Eddy
TL Liikala
VL McGhan
LS Prater
MR Quarders
JR Raymond
JT Rieger
PD Thorne
File/LB

Date October 24, 1983

To PE Bramson

From EL Hilty PAE for ELH

Subject Monthly Report - October 1983

Well Maintenance:

1. The JAJ road construction crew that I was "bird-dogging" for Keith Price completed work on access inprovements to three air sampler sites and one sample well site near 200-E Area this report period. We are currently waiting for another cost estimate before continuing more of this type work.

2. The construction of a security fence around our equipment storage site at the Met Tower Quonset Hut has been completed.

3. The 5 hp aquifer test pump was removed from 699-2-3 and the larger 7-1/2 hp pump installed.

4. I installed, and tested, eight sample pumps in newly drilled wells in 100-N Area. These wells are designated 100N-27 thru N-34 and surround the new #1325-N crib.

5. More problem wells were routinely pumped this report period to reduce "sanding" problems.

6. Vehicle 1H-776 has been stranded at 100 H since October 21 with tire blowout problems. For reasons too numerous to mention, the tire repair people at the 1100 Area garage have been unable to help. I am now in lengthy negotiation with the 200 West tire repair people - stay tuned!

7. UNC wants me to check the three new 100-H wells and determine if the sample pumps installed by the drilling contractor meet with our approval. I will do so upon repair of my truck.

ELH:ks