e. 699-S6-E14 = A broken pipe column was repaired.

f. 699-40-33 = A sample pump was reinstalled.

g. 699-72-88 = A colony of bees had built a hive in the casing and were removed. A broken pipe column was also repaired.

7. Three sample pumps that had been taken out of service for repair are now available for reinstallation.